## Approved For Refers - 2006/03/03 CIA-RDP82-00457R003800270009-6

	CLASSIFICATIO	N SECRET/CORTECL/US OF ICA IS ONLY
COUNTRY Soviet	Zone of Germa	REPORT
TOPIC DESSAU	Airfield	25X1
and the second s		
EVALUATION	25X1	PLACE OBTAINED.
DATE OF CONTENT		25X1 25X1
DATE OBTAINED		DATE PREPARED 1 November 1949
REFERÊNCES	25X1	
PAGES 2	_ENCLOSURES (NO	. & TYPE) 1 diagram
REMARKS		
4		RETURN TO CIA LIBRARY
iki keren. A Mile Cile kilaya da ilindakan pelabuha di Kabbalan Kabbalan Kabbalan da dalah da daban da baban d	nank. Wasterner e district and real party as a superior game and a	

- 1. Improvements were being made at the DESSAU (M 52/E 08) airfield. About two hundred workers were engaged in reconditioning and extending the texiway.\* Ditches, 10 to 16 feet wide
  and 10 to 13 feet deep, were being excavated in the northern
  section of the airfield, starting almost in the middle of
  the field, and extending toward the runway.\* Two railroad
  tank cars were standing on the spur track. Obstacle lights
  were in operation at night. The boundary lights were destroyed. No radio station was observed.
  - 2. Two biplanes and thirty-six single-engine fighters were parked on the eastern edge of the field. Of these fighters, 24 had red and 3 blue propeller hubs. Description of the 27 fighters:\*\*

hadial engine, three-bladed propeller, large propeller hub, trapezoidal wings slightly dihedral. Straight trailing edge of elevator assembly, triangular rudder assembly with rounded-off trailing edge, landing gear and tail wheel retractable, the latter covered with sheet metal. Letached single-seat cockpit with rear section fairing into fuselage. Device, similar to a searchlight, apparently a Revi, forward of cockpit (see Annex). Cut, similar to machine gun or cannon aperture, in engine cowling, static tube at right wing, antenna leading to rudder assembly, stubby and clumsy fuselage. Bomb rack or extra tank at bottom of fuselage, almost at center of gravity (suspension hook and side brace). Radiator at bottom of fuselage

25X1 in line with trailing edge of wings,

Some planes had two diagonal red stripes on a yellow field on the rudder assembly.


25X1

25X1

25X1

There were six more aircraft with two-seat cockpits, no bomb rack under fuselage, radiator under fuselage in line with center of wines, red propeller bubs

same type had a somewhat lower landing gear and two-bladed propellers.



4.	Eighty to a hundred air force officers arrived by truck and
	bus from ALTEN (3 52/E 06) at 12:30 p.m. There was flying
	with 18 aircraft. These single-seat fighters took off in
	elements of two from the sodded landing field and later
	landed individually. The two-seat fighters individually
	circled the airfield.

25X1 Comment:

\* a. The construction work on the taxiway (probably extension in accordance with lengthening of the runway) was confirmed.

The excavation of deep ditches in the northern section of the airfield was reported for the first time. Fuel containers are possibly to be installed there.

\*\* b. Report confirms observation on 21 September 1949 of the occupation of the airfield by a fighter unit. According to the description of the aircraft, the unit is equipped with LA-9s.

1 Annex: Partial Side View of righter Aircraft Observed at the DESSAU Airfield.

25X1

25X1


CONFIDENTIAL

CECHAT-CONTROL/ US OFF ICIALS ONLY

## CONFIDENTIAL

SHORET/CONTROL - U.S. OFFICIALS ONLY 25X1

Partial Side View of Fightor Aircraft Observed at the Dessau Airfield



CONFIDENTIAL

-SECRET/CONTROL - U.S. OFFICIALS ONLY